

ITEM NO.	PART NO.	DESCRIPTION	QTY. REQ'D		ITEM NO.	PART NO.	DESCRIPTION
1		Drive Cap Assemblies			3g	201317	Lower Housing (Metallic Fuchsia)
1a	200362	Drive Cap Assembly (Pink)	1		3h	201389	Lower Housing (Black)
1b	200363	Drive Cap Assembly (Metallic Silver)	1	4		60802	Switch Button
1c	200364	Drive Cap Assembly (Metallic Blue)	1	5		13618	Motor Assembly
1d	200366	Drive Cap Assembly (Lime Green)	1	6		S20656	Blade Drive Assembly
1e	200367	Drive Cap Assembly (Purple)	1	7		15766	Blade Drive Screw
1f	200368	Drive Cap Assembly (Metallic Black)	1	8		S63897	Hinge Assembly
1g	200369	Drive Cap Assembly (Black)	1	9		64535	Lock Keeper
1h	201497	Drive Cap Assembly (Burgundy)	1	10)	27864	Blade Hinge Screw
1i	201498	Drive Cap Assembly (Metallic Fuchsia)	1	11		60801	Circuit Board
2		Upper Housing		12	!	65828	Screw
2a	201076	Upper Housing (Pink)	1	13	1	60701	Insulator
2b	201077	Upper Housing (Metallic Silver)	1	14		64940	Cord Set
2c	201083	Upper Housing (Metallic Blue)	1	15		25542	Hanger Bail
2d	201084	Upper Housing (Lime Green)	1	16	i	64606	Front Housing Screw
2e	201086	Upper Housing (Purple)	1	17	,	60804	Rear Housing Screws
2f	201314	Upper Housing (Burgundy)	1	18	}	64003	Blade Bracket
2g	201316	Upper Housing (Metallic Fuchsia)	1	19)	64013	Tension Spring
2h	201388	Upper Housing (Black)	1	20)	64027	Blade Guide
3		Lower Housing		21		64139	Blade Screw
3a	201089	Lower Housing (Pink)	1				
3b	201091	Lower Housing (Metallic Silver)	1				
3с	201097	Lower Housing (Metallic Blue)	1				
3d	201098	Lower Housing (Lime Green)	1				
3e	201099	Lower Housing (Purple)	1				
3f	201315	Lower Housing (Burgundy)	1				

IMPORTANT INFORMATION

When ordering repair parts, include part number, part name and model of trimmer. For best performance, trimmer blades should be CLEANED and OILED with Andis Clipper Oil before and after use, If repair is necessary, return to any Andis Authorized Repair Service Station, or to Andis Company, 1800 Renaissance Blvd., Sturtevant, Wisconsin, 53177 U.S.A.. Pack carefully, mail either Insured Parcel Post, or U.P.S., attach a letter to outside of package explaining difficulty.

FORM 13654 SERVICE CENTER

QTY. REQ'D

1

2